

G-5 礦場安全檢查次數及處理

年別	石油、天然氣礦業									
	檢查結果(礦次) Inspection Result(Number)					應行改善項目次數(次) Items Ought to be Improved(Number)				
	合 計 Total	第三類 (危險) Class 3 Dangerous	第二類 (次危險) Class 2 Sub- dangerous	第一類 (較安全) Class 1 Safer	自 動 停 工 Suspended	合 計 Total	通 風 Ventilation	防火防水 及 廢 石 Prevention of Fire, Flood and Roof-fall	機 電 Elec. and Mech. Apparatus	採掘面 Working Face
104年	120	-	-	120	-	128	-	-	-	-
105年	127	-	-	125	2	82	-	-	-	-
106年	126	-	-	126	-	80	-	1	5	-
107年	151	-	-	143	8	128	-	-	2	-
108年	117	-	-	117	-	126	-	4	1	-
109年	161	122	-	...	-	-
110年	111	92	-	...	-	-

資料來源：經濟部礦務局。

G-5 Mine Safety Supervising Inspections

Crude Petroleum and Natural Gas Extraction											Period
應行改善項目次數 (次) Items Ought to be Improved (Number)						處分情形 (礦次) Executive Situation (Number)					
搬 運 Haulage	保 坑 Pit Maintenance	炸 藥 Explosives	有害瓦斯 Toxic Gas	坑內溫度 Pit Temperature	安全管理 Safety Supervision	全 停 Completely Suspended	局部停採 Partly Stopped for Coal Mining	局部停進 Partly Stopped for Heading Advance	機件停用 Certain Machine Suspended		
-	-	-	-	-	128	-	-	-	-	-	2015
-	-	-	-	-	82	-	-	-	-	-	2016
-	-	-	-	-	74	-	-	-	-	-	2017
-	-	-	-	-	126	-	-	-	-	-	2018
-	-	-	-	-	121	-	-	-	-	-	2019
-	-	-	-	-	117	-	-	-	-	-	2020
-	-	-	-	-	92	-	-	-	-	-	2021

Source : Bureau of Mines, M. O. E. A. .

G-5 礦場安全檢查次數及處理(續)

年別	砂、石採取及其他礦業									
	檢查結果(礦次) Inspection Result(Number)					應行改善項目次數(次) Items Ought to be Improved(Number)				
	合 計	第三類 (危險)	第二類 (次危險)	第一類 (較安全)	自 動 停 工	合 計	通 風	防火防水 及 廢 石	機 電	採掘面
Total	Class 3 Dangerous	Class 2 Sub- dangerous	Class 1 Safer	Suspended	Total	Ventilation	Prevention of Fire, Flood and Roof-fall	Elec. and Mech. Apparatus	Working Face	
104年	2 162	-	-	1 504	658	1 558	29	16	180	311
105年	2 120	-	-	1 395	725	1 180	23	11	107	191
106年	2 077	-	-	1 381	696	1 222	16	18	104	187
107年	1 698	-	-	1 192	506	1 361	22	43	112	191
108年	1 710	-	59	1 529	122	1 255	30	14	101	171
109年	1 679	1 157	34	...	122	117
110年	1 409	841	16	...	103	91

資料來源：經濟部礦務局。

G-5 Mine Safety Supervising Inspections(Cont.)

Sand, Stone Quarrying and Other Mining											Period
應行改善項目次數 (次) Items Ought to be Improved (Number)						處分情形 (礦次) Executive Situation (Number)					
搬 運 Haulage	保 坑 Pit Maintenance	炸 藥 Explo-sives	有害瓦斯 Toxic Gas	坑內溫度 Pit Temperature	安全管理 Safety Super-vision	全 停 Completely Suspended	局部停採 Partly Stopped for Coal Mining	局部停進 Partly Stopped for Heading Advance	機件停用 Certain Machine Suspended		
201	60	-	-	5	756	-	-	-	-	2015	
93	31	1	-	5	718	-	-	-	-	2016	
83	45	1	-	-	768	-	1	-	2	2017	
93	59	-	2	-	839	-	-	-	-	2018	
106	44	-	-	-	789	7	9	-	2	2019	
105	56	-	-	-	714	12	1	1	2	2020	
73	45	2	-	-	505	-	-	-	-	2021	

Source : Bureau of Mines, M. O. E. A. .